

## SERVICE BULLETIN

No. 1118-E					
Name of Product	EIGHT BALL				
Effective	All Games				

October 1, 1977

THE FOLLOWING IS A LIST OF CORRECTIONS TO BE MADE ON ALL EIGHT BALL SCHEMATICS:

## Schematic W-1182-3c

- A. Next to R68, ADD R69
- B. On J3, change J3-3 to S.P.S.A: J3-13 to CREDIT IND.
- C. Change

R8 R9 R10 R11 R4	to to to to	R16 R17 R18 R8 R7	R1 R2 R3 R7 R16	to to to to	R6 R5 R4 R1 R20	R5 R6 R35 R34 R22	to to to to	R3 R2 R36 R35 R31
R26 R25 R24 R17 R23	to to to to	R23 R22 R33 R21 R32	R21 R15 R18 R19 R33	to to to	R9 R19 R15 R11 R34	R31 R36 R38 R44 R49	to to to to	R26 R45 R41 R43 R52
R48 R37 R32 R20 R42	to	R51 R38 R25 R10 R47	R41 R40 R39 R47 R43	to to to	R48 R46 R24 R49 R44	R45 R50 R51 R54 R55	to to to to	R42 R55 R56 R58 R59
R60 R59 R58 R56 R46	to to to to	R54 R53 R50 R60 R40	R52 R53		R37 R39			

## Schematic W-1186-3, Sheet 2 of 3, top middle: +43VDC bus line (effective game serial #1907):

- A. Change 30 to 60, A2J1-6 (Wire Color Code)
- B. Add fuse, +43VDC bus, between right flipper and outhole ball eject coils



## SERVICE BULLETIN

No. 1118-E

Name of Product EIGHT BALL

Effective All Games

October 1, 1977

Page 2

- C. Add fuse description, "1 Amp, S.B., E-133-44". Substitutions other than BALLY part number not recommended
- D. Outhole side of fuse, wire color is 30

Schematic W-1186-3, Sheet 1 of 3, effective game serial #1907:

A. A2J1, Pin 6, change color 30 to 60

B.M. Powers Field Service Manager

Page 2 of 2